

# Oil Field Environmental Incident Summary

**Incident:** 20140811110655 **Date/Time of Notice:** 08/11/2014 11:06

**Responsible Party:** HUNT OIL COMPANY

**Well Operator:** HUNT OIL COMPANY

**Well Name:** PALERMO 1-2-31H

**Field Name:** ROSS

**Well File #:** 19071

**Date Incident:** 8/10/2014 **Time Incident:** 13:45

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 156

**Rng:** 90

**Sec:** 2

**Qtr:**

**Location Description:** North wind was blowing creating a mist that carried into Landowners pasture/grass field covering and area 80'w x 60'l.

**Submitted By:** Booger Morris

**Received By:**

**Contact Person:** Booger Morris

1900 NORTH AKARD STREET

DALLAS, TX 75201-2300

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	9	Barrels	9	Barrels	9	barrels
Brine	1	Barrels	1	Barrels	1	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/2/2014

**Clean Up Concluded:** 8/14/2014

**Risk Evaluation:**

No immediate risk due to well ventilated area.

**Areal Extent:**

60' x 80' area impacted off location.

**Potential Environmental Impacts:**

Impacted grassy area off site of location, grass has been cut and removed and top soil on location has been removed and will be replaced by fresh soil.

**Action Taken or Planned:**

The well was shut down with the treater being isolated to remove any pressure from the vessel. A transport truck from Key was able to be on location within ten (10) minutes and start removing the fluid. We then had a super-vac from North Country come to remove as much contaminated soil/rock as possible, once they finished JMAC were on location. JMAC was able to cut and remove the misted grass, the hill side matting, and any stained dirt/rock that North Country were unable to remove. The clean up plan is to remove all contaminated soil/grass/rocks, we will reseed and replace all contaminated soil.

**Wastes Disposal Location:** Indian Hills Disposal

**Agencies Involved:****Updates**

---

**Date:** 8/13/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release sprayed off location. Report indicates vegetation and topsoil removal. Followup is necessary to confirm adequate cleanup.

---

**Date:** 8/14/2014    **Status:** Reviewed - No Action Required

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Visited site and met Booger Morris with Hunt Oil Co. The 80' X 60' impact area had been scraped clean, and vegetation and topsoil had been disposed of. According to Mr. Morris, the landowner would like him to wait until October to reseed the area in order to obtain better germination. The area is hay field. Hunt Oil will reseed in accordance with the landowner's wishes. No additional work is warranted, and site should be closed.